

Oil Field Environmental Incident Summary

Incident: 20150808170357

Date/Time of Notice: 08/08/2015 17:03

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BRADAC CTB

Field Name: CEDAR HILLS

Well File #:

Date Incident: 8/8/2015

Time Incident: 06:45

Facility ID Number: 413779-02

County: BOWMAN

Twp: 132

Rng: 106

Sec: 29

Qtr: NE NE

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Terry Staub

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

fire

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

Tank shut in and drained. Standing oil sucked up. Contaminated soil recovery in progress. Gasket will be inspected to determine if the it was defective or if the installation wasn't done properly.

Wastes Disposal Location: Liquid - returned to tanks
Soil - Little Missouri Landfill

Agencies Involved: Matt Tibor, NDIC - Left message
Richard Dunn, NDIC - Left message

Updates

Date: 8/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained within the diking according to the report. NDIC retains oversight.